
Kevin Berni (B269580) Ogden, UT



This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 11/8/24 at 4:06:55 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

<b>CARFAX</b> Additional History Not all accidents / issues are reported to CARFAX	Owners 1-2	Owner 3	Owner 4
<b>Total Loss</b> No total loss reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
<b>Structural Damage</b> No structural damage reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
<b>Airbag Deployment</b> No airbag deployment reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
<b>Odometer Check</b> No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated	No Issues Indicated
<b>Accident / Damage</b> No accidents or damage reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Volkswagen dealer to obtain more information about this recall.	Recall Reported	No New Recalls Reported	No New Recalls Reported

CARFAX Vehicle History Report for this 2015 VOLKSWAGEN JETTA S: 3VW2K7AJ6FM269531

<b>Basic Warranty</b> Original warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

<b>CARFAX Title History</b> CARFAX guarantees the information in this section	Owners 1-2	Owner 3	Owner 4
<b>Damage Brands</b>	Guaranteed	Guaranteed	Guaranteed
Salvage   Junk   Rebuilt   Fire   Flood   Hail	No	No	No
Lemon	Problem	Problem	Problem
<b>Odometer Brands</b>	Guaranteed	Guaranteed	Guaranteed
Not Actual Mileage   Exceeds Mechanical	No	No	No
Limits	Problem	Problem	Problem



**GUARANTEED** - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify. View Terms

<b>CARFAX Ownership History</b> The number of owners is estimated	Owners 1-2	Owner 3	Owner 4
Year purchased	2015	2019	2023
Type of owner	See Details	Personal	Personal
Estimated length of ownership	4 yrs. 4 mo.	3 years	1 yr. 7 mo.
Owned in the following states/provinces	See Details	California	Utah
Estimated miles driven per year	See Details	2,100/yr	
Last reported odometer reading	67,390	74,083	78,628

## **CARFAX** Detailed History

<b>Owne</b> Purch	<b>r 1</b> ased: 2015		Rental Vehicle 25,595 mi/yr
Date	Mileage	Source	Comments
02/28/201	15	NICB	Vehicle manufactured and shipped to original dealer
03/02/201	15	Florida Motor Vehicle Dept. Orlando, FL	<b>Registration issued or renewed</b> - Titled or registered as rental vehicle - Vehicle color noted as Red
03/25/201	15 10	California Motor Vehicle Dept.	Odometer reading reported

https://www.carfaxbig.com/report/vhr?vin=3VW2K7AJ6FM269531&referenceNumber=

4, 3:07 PM		CARFAX Vehicle History Report fo Orlando, FL	n uns 2013 v	OLKSWAGEN JETTA 5. 5	V VVZK / AJOFINIZO955 I
03/27/2015		Florida Motor Vehicle Dept. Orlando, FL		<b>Registration issu</b> - Vehicle color no	<b>ied or renewed</b> ited as Red
04/14/2015		California Motor Vehicle Dept. Orlando, FL		<b>Title issued or u</b> - First owner repo - Loan or lien repo	orted
12/27/2016		California Motor Vehicle Dept. Orlando, FL			ated when owner le to a new location
01/30/2017	49,088	Auto Auction		Vehicle sold	
		CAR		lions of used vehicle ction every year.	es are bought and sold at
02/10/2017	49,104	California Inspection Station		Passed emissior	is inspection
<b>Owner 2</b> Purchase		Low mileage! T than the industr miles per year.			
		than the industr			Personal Vehic 8,263 mi/
Purchase	ed: 2017	than the industri miles per year.		e of 15,000	8,263 mi/ <u>y</u>
Purchase Date	ed: 2017	than the industri miles per year. Source California Motor Vehicle Dept.		e of 15,000 Comments	8,263 mi/ <u>y</u> og reported odated orted
Purchase Date 05/01/2017	ed: 2017	than the industri miles per year. Source California Motor Vehicle Dept. Loma Linda, CA California Motor Vehicle Dept.		e of 15,000 Comments Odometer readin Title issued or up - New owner repo	8,263 mi/ <u>y</u> og reported orted orted orted
Purchase Date 05/01/2017 05/16/2017	ed: 2017 Mileage 49,174	than the industri miles per year. Source California Motor Vehicle Dept. Loma Linda, CA California Motor Vehicle Dept. Loma Linda, CA California		e of 15,000 Comments Odometer readin Title issued or up - New owner repo - Loan or lien repo Vehicle recovere - Vehicle towed Vehicle serviced	8,263 mi/ <u>y</u> og reported orted orted orted
Purchase <b>Date</b> 05/01/2017 05/16/2017 10/03/2017	ed: 2017 Mileage 49,174	SourceCalifornia Motor Vehicle Dept. Loma Linda, CACalifornia Motor Vehicle Dept. Loma Linda, CACalifornia Stolen ReportAudi Bakersfield Bakersfield, CA	ry average	e of 15,000 Comments Odometer readin Title issued or up - New owner repo - Loan or lien repo Vehicle recovere - Vehicle towed Vehicle serviced	8,263 mi/y og reported orted orted orted d after theft
Purchase <b>Date</b> 05/01/2017 05/16/2017 10/03/2017	ed: 2017 Mileage 49,174	than the industr miles per year. Source California Motor Vehicle Dept. Loma Linda, CA California Motor Vehicle Dept. Loma Linda, CA California Stolen Report Audi Bakersfield Bakersfield, CA 661-617-6200 ★ 4.1 / 5.0 8 Verified Reviews	ry average	e of 15,000 Comments Odometer readin Title issued or up - New owner repo - Loan or lien repo Vehicle recovere - Vehicle towed Vehicle serviced	8,263 mi/y

-0il and filter changed - Tire(s) balanced         04/12/2019       California Motor Vehicle Dept. Barstow, CA       Registration updated when owner moved the vehicle to a new location         05/13/2019       California Motor Vehicle Dept. Barstow, CA       Title issued or updated -Loan or lien reported         07/08/2019       67,241       Auto Auction       Vehicle sold         08/27/2019       Volkswagen       Manufacturer Compliance Recall issued -NHTSA #19V615 - Recall #37M2 MICRO SWITCH - Status: Remedy Available         Locarte an authorized Volkswagen dealer to obtain more information ab this recall       Cole Learn more about this recall         O Escription: Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle mocompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle mocompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition switch and circuit board.         09/16/2019       67,317       Auto Auction       Vehicle sold         09/30/2019       67,317       Auto Auction       Vehicle offered for sale         09/16/2019       <	the P pa park. Th preventi there is damage <b>Remedy</b> 09/16/201 09/30/201 10/03/201	on. If the ign a risk that th property. : Install an a 9 67,317 9 67,390 9 9 r <b>3</b> ased: 2019	dditional swit Auto Auctic California Inspection Dealer Inve	tch and circuit board on Station ntory .ow mileage! This owned han the industry average	in a crash that co d. Vehicle sold Passed emission Vehicle offered er drove less je of 15,000	P Park position, buld injure people and ons inspection
-0il and filter changed - Tire(s) balanced         04/12/2019       California Motor Vehicle Dept. Barstow, CA       Registration updated when owner moved the vehicle to a new location         05/13/2019       California Motor Vehicle Dept. Barstow, CA       Title issued or updated -Loan or lien reported         07/08/2019       67,241       Auto Auction       Vehicle sold         08/27/2019       Volkswagen       Manufacturer Compliance Recall issued -NHTSA #19V615 - Recall #37M2 MICRO SWITCH - Status: Remedy Available Locate an authorized Volkswagen dealer to obtain more information ab this recall         Oescription: Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle morcompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.         09/16/2019       67,317       Auto Auction       Vehicle sold         09/30/2019       67,390       California Inspection Station       Passed emissions inspection         10/03/2019       Dealer Inventory       Vehicle offered for sale <th>the P pa park. Th preventi there is damage <b>Remedy</b> 09/16/201 09/30/201 10/03/201</th> <th>on. If the ign a risk that th property. : Install an a 9 67,317 9 67,390 9</th> <th>dditional swit Auto Auctio California Inspection Dealer Inve</th> <th>tch and circuit board on Station ntory .ow mileage! This owned han the industry average</th> <th>in a crash that co d. Vehicle sold Passed emission Vehicle offered</th> <th>on P Park position, build injure people and ons inspection for sale Personal Vehicl</th>	the P pa park. Th preventi there is damage <b>Remedy</b> 09/16/201 09/30/201 10/03/201	on. If the ign a risk that th property. : Install an a 9 67,317 9 67,390 9	dditional swit Auto Auctio California Inspection Dealer Inve	tch and circuit board on Station ntory .ow mileage! This owned han the industry average	in a crash that co d. Vehicle sold Passed emission Vehicle offered	on P Park position, build injure people and ons inspection for sale Personal Vehicl
04/12/2019       California Motor Vehicle Dept. Barstow, CA       Registration updated when owner moved the vehicle to a new location         05/13/2019       California Motor Vehicle Dept. Barstow, CA       Title issued or updated - Loan or lien reported         07/08/2019       67,241       Auto Auction       Vehicle sold         08/27/2019       Volkswagen       Manufacturer Compliance Recall issued - NHTSA #19V615 - Recall #37M2 MICRO SWITCH - Status: Remedy Available         Description: Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition akey is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.         09/16/2019       67,317       Auto Auction       Vehicle sold         09/16/2019       67,390       California Inspection Station       Passed emissions inspection	the P pa park. Th preventi there is damage <b>Remedy</b> 09/16/201	on. If the ign a risk that th property. : Install an a 9 67,317 9 67,390	dditional swit Auto Auctio California Inspection	tch and circuit board	in a crash that co I. Vehicle sold Passed emissio	P Park position, buld injure people and ons inspection
-0il and filter changed -Tire(s) balanced         04/12/2019       California Motor Vehicle Dept. Barstow, CA       Registration updated when owner moved the vehicle to a new location         05/13/2019       California Motor Vehicle Dept. Barstow, CA       Title issued or updated -Loan or lien reported         07/08/2019       67,241       Auto Auction       Vehicle sold         08/27/2019       Volkswagen       Manufacturer Compliance Recall issued - NHTSA #19V615 - Recail #37M2 MICRO SWITCH - Status: Remedy Available         Description: Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in n the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.         09/16/2019       67,317       Auto Auction       Vehicle sold         09/30/2019       67,390       California       Passed emissions inspection	the P park. Th park. Th preventi there is damage <b>Remedy</b> 09/16/201	on. If the ign a risk that th property. : Install an a 9 67,317	e vehicle may dditional swit Auto Auctic California	tch and circuit board	in a crash that co d. <b>Vehicle sold</b>	n P Park position, buld injure people and
-Oil and filter changed -Tire(s) balanced         04/12/2019       California Motor Vehicle Dept. Barstow, CA       Registration updated when owner moved the vehicle to a new location         05/13/2019       California Motor Vehicle Dept. Barstow, CA       Title issued or updated -Loan or lien reported         07/08/2019       67,241       Auto Auction       Vehicle sold         08/27/2019       Volkswagen       Manufacturer Compliance Recall issued - NHTSA #19V615 - Recall #37M2 MICRO SWITCH - Status: Remedy Available         Locate an authorized Volkswagen dealer to obtain more information ab this recall       Otain more information ab this recall         Osceription: Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in P park. This makes the vehicle noncompliant with FMVSS 114 Theft protection and rollaway prevention. If the ignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.         Remedy: Install an additional switch and circuit board.	the P pa park. Th preventi there is damage <b>Remedy</b>	on. If the ign a risk that th property. : Install an a	e vehicle may dditional swit	tch and circuit board	in a crash that co I.	n P Park position,
- Oil and filter changed - Tire(s) balanced         04/12/2019       California Motor Vehicle Dept. Barstow, CA       Registration updated when owner moved the vehicle to a new location         05/13/2019       California Motor Vehicle Dept. Barstow, CA       Title issued or updated -Loan or lien reported         07/08/2019       67,241       Auto Auction       Vehicle sold         08/27/2019       Volkswagen       Manufacturer Compliance Recall issued - NHTSA #19V615 - Recall #37M2 MICRO SWITCH - Status: Remedy Available         Locate an authorized Volkswagen dealer to obtain more information ab this recall       Otexern more about this recall         Description: Over time, a build up of silicate on the shift lever micro switch contacts can result in an isolation like layer that may be interpreted as an open micro switch. This open switch normally indicates that the shift lever is in P park position. If the build up happens, it may be possible to remove the key from the ignition switch without the shift lever being in the P park position because the system is unable to recognize that the vehicle is not in P park. This makes the vehicle morcompliant with FMVSS 114 Theft protection and rollaway prevention. If the lignition key is removed without the shift lever being in P Park position, there is a risk that the vehicle may roll away, resulting in a crash that could injure people and damage property.	the P pa park. Th preventi there is damage	on. If the ign a risk that th property.	e vehicle may		in a crash that co	n P Park position,
-Oil and filter changed         -Tire(s) balanced         04/12/2019       California Motor Vehicle Dept. Barstow, CA       Registration updated when owner moved the vehicle to a new location         05/13/2019       California Motor Vehicle Dept. Barstow, CA       Title issued or updated -Loan or lien reported         07/08/2019       67,241       Auto Auction       Vehicle sold         08/27/2019       Volkswagen       Manufacturer Compliance Recall issued - NHTSA #19V615 - Recall #37M2 MICRO SWITCH - Status: Remedy Available         Locate an authorized Volkswagen dealer to obtain more information ab	result in switch n	an isolation ormally indic possible to r rk position b	like layer tha cates that the emove the ke because the s e vehicle none	t may be interpreted e shift lever is in P pa ey from the ignition s ystem is unable to r compliant with FMVS	C Learn more ift lever micro sw as an open micro ark position. If the witch without the ecognize that the SS 114 Theft prot	itch contacts can o switch. This open build up happens, it shift lever being in vehicle is not in P
Oil and filter changed - Tire(s) balanced04/12/2019California Motor Vehicle Dept. Barstow, CARegistration updated when owner moved the vehicle to a new location05/13/2019California Motor Vehicle Dept. Barstow, CATitle issued or updated - Loan or lien reported	08/27/201	9	Volkswage	n	issued - NHTSA #19V6 - Recall #37M2 - Status: Remed Locate an autho dealer to obtain	15 MICRO SWITCH y Available prized Volkswagen
- Oil and filter changed - Tire(s) balanced         04/12/2019       California Motor Vehicle Dept. Barstow, CA       Registration updated when owner moved the vehicle to a new location         05/13/2019       California Motor Vehicle Dept.       Title issued or updated - Loan or lien reported	07/08/201	9 67,241	Auto Auctio	on	Vehicle sold	
04/12/2019       California Motor Vehicle Dept.       Registration updated when owner moved the vehicle to a new location	05/13/201	9	Motor Vehi			•
- Oil and filter changed	04/12/201	9	Motor Vehi	•		
04/02/2019 66,982 Service Facility Vehicle serviced				cility	- Tire(s) replace - Oil and filter ch	d anged

https://www.carfaxbig.com/report/vhr?vin=3VW2K7AJ6FM269531&referenceNumber=

3/24, 3:07 PM		CARFAX Vehicle History Report for the Motor Vehicle Dept. Lemon Grove, CA	is 2015 \	/OLKSWAGEN JETTA S: 3VW2K7AJ6FM269531
12/05/2019		California Motor Vehicle Dept. Lemon Grove, CA		<b>Title issued or updated</b> - New owner reported - Loan or lien reported
03/06/2020	68,348	Eastlake Shell Chula Vista, CA 619-656-1107 <b>4.8 / 5.0</b> 93 Verified Reviews <b>76</b> Customer Favorites	╳	<b>Vehicle serviced</b> - Maintenance inspection completed - Vehicle washed/detailed - Engine checked - Oil and filter changed
09/18/2020	69,287	Pep Boys Chula Vista, CA 619-216-4604 <b>4.4 / 5.0</b> 274 Verified Reviews <b>162</b> Customer Favorites	×	<b>Vehicle serviced</b> - Tire(s) balanced - Tire(s) mounted
02/14/2021		Pep Boys Chula Vista, CA 619-216-4604	×	<b>Vehicle serviced</b> - Tire(s) balanced - Tire repaired
04/02/2021	70,661	Eastlake Shell Chula Vista, CA 619-656-1107 <b>4.8 / 5.0</b> 93 Verified Reviews <b>76</b> Customer Favorites	╳	<b>Vehicle serviced</b> - Maintenance inspection completed - Vehicle washed/detailed - Engine checked - Oil and filter changed
04/27/2021		California Motor Vehicle Dept. Lemon Grove, CA		<b>Title issued or updated</b> - Loan or lien reported
07/07/2021	71,495	Pep Boys Chula Vista, CA 619-216-4604 <b>4.4 / 5.0</b> 274 Verified Reviews <b>162</b> Customer Favorites	×	<b>Vehicle serviced</b> - Alignment checked - Tire(s) balanced - Tire(s) mounted
05/11/2022	73,351	Eastlake Shell Chula Vista, CA 619-656-1107 <b>the description</b> 93 Verified Reviews	×	<b>Vehicle serviced</b> - Maintenance inspection completed - Vehicle washed/detailed - Engine checked - Oil and filter changed

CARFAX Vehicle History Report for this 2015 VOLKSWAGEN JETTA S: 3VW2K7AJ6FM269531

		<b>76</b> Customer Favorites	
10/18/2022		California Motor Vehicle Dept. Lemon Grove, CA	<b>Title issued or updated</b> - Loan or lien reported
11/28/2022	73,886	Auto Auction	Vehicle sold
01/30/2023	74,071	Auto Auction	<b>Vehicle sold</b> - Listed as a dealer vehicle
02/05/2023		Ken Garff Buick GMC Riverdale Ogden, UT 801-627-6700	Vehicle offered for sale
02/28/2023	74,083	Ken Garff Buick GMC Riverdale Ogden, UT 801-627-6700 ★ 4.6 / 5.0 133 Verified Reviews ♥ 112 Customer Favorites	<ul> <li>Vehicle serviced</li> <li>Pre-delivery inspection completed</li> <li>Wiper(s) replaced</li> <li>Oil and filter changed</li> <li>Four wheel alignment performed</li> <li>Vehicle washed/detailed</li> </ul>
		CAP FOX	Looks like this dealer serviced the car in order to prepare it for sale. That's a good thing!
03/04/2023		Utah Motor Vehicle Dept.	Vehicle purchase reported
03/20/2023		Utah Inspection Station	Passed emissions inspection
• Owner 4 Purchase	d: 2023		Personal Vehic
Date	Mileage	Source	Comments
03/20/2023		Utah Motor Vehicle Dept. Roy, UT	<b>Registration issued or renewed</b> - New owner reported - Loan or lien reported - Passed safety inspection - Vehicle color noted as Red
03/20/2023 04/06/2023		Motor Vehicle Dept.	- New owner reported - Loan or lien reported - Passed safety inspection

https://www.carfaxbig.com/report/vhr?vin=3VW2K7AJ6FM269531&referenceNumber=

11/8	/24, 3:07 PM		CARFAX Vehicle History Report for th Motor Vehicle Dept. Roy, UT Title #E001199535UT	is 2015 \	OLKSWAGEN JETTA S: 3VW2K7AJ6FM269531 - Loan or lien reported - Vehicle color noted as Red
	07/21/2023	78,628	Ken Garff Honda Riverdale Ogden, UT 801-781-4700 ★ 4.7 / 5.0 273 Verified Reviews ♥ 220 Customer Favorites	×	Vehicle serviced - Maintenance inspection completed - Fluids checked - Oil and filter changed - Tires rotated - Body lubricated
	06/17/2024		Ken Garff Buick GMC Riverdale Ogden, UT 801-627-6700 ★ 4.6 / 5.0 133 Verified Reviews ♥ 112 Customer Favorites	×	Vehicle serviced
-	10/28/2024		Utah Inspection Station		Passed emissions inspection
	10/28/2024		Utah Motor Vehicle Dept. Roy, UT Title #UT010989893		<b>Title issued or updated</b> - Duplicate title issued - Vehicle color noted as Red
	Have Que		onsumers, please visit our H pers, please visit our Help C		enter at www.carfax.com. Dealers or at www.carfaxonline.com.

# **CARFAX** Glossary

### **First Owner**

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

### **Manufacturer Recall**

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

### **New Owner Reported**

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

#### **Ownership History**

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

### Rental

Vehicle was registered by a rental agency.

### **Title Issued**

CARFAX Vehicle History Report for this 2015 VOLKSWAGEN JETTA S: 3VW2K7AJ6FM269531

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:

facebook.com/CARFAX







CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2024 CARFAX, Inc., part of S&P Global. All rights reserved. 11/8/24 4:06:55 PM (CST)